DOCKET NO.: FCI-2656/C3138 PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In Re Application of:

Clifford Winings Confirmation No.: 3955

Patent No.: 7,059,907 Issued: June 13, 2006

Application No.: 10/626,960 Filing Date: July 24, 2003

For: Modular Electrical Connector

Commissioner for Patents Attn: Certificate of Correction Branch P.O. Box 1450

Alexandria, VA 22313-1450

Dear Sir:

REQUEST FOR SECOND CERTIFICATE OF CORRECTION OF PATENT FOR APPLICANT'S MISTAKE PURSUANT TO 37 CFR § 1.323

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. The patent has error(s) in it that occurred through applicant's fault. Applicant's error(s) occurred in good faith and are of a clerical or typographical nature, or minor character, and are not believed to constitute new matter or require examination.

Enclosed herewith please find a completed Certificate of Correction form in duplicate.

	Please charge Deposit Account No. 23-3050 in the amount of \$.00 . This sheet is attached in duplicate. (See 37 CFR § 1.20(a))
\boxtimes	A check in the amount of \$100.00 is attached.
\boxtimes	The Commissioner is hereby authorized to charge any deficiency or credit any overpayment of the fees associated with this communication to Deposit Account No. 23-3050.

DOCKET NO.: FCI-2656/C3138 PATENT

Date: August 27, 2008

/Joseph R. Condo/ Joseph R. Condo Registration No. 42,431

Woodcock Washburn LLP Cira Centre 2929 Arch Street, 12th Floor Philadelphia, PA 19104-2891 Telephone: (215) 568-3100 Facsimile: (215) 568-3439 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page <u>1</u> of <u>1</u>
PATENT NO. : 7,059,907B2
APPLICATION NO.: 10/626,960
ISSUE DATE : June 13, 2006
INVENTOR(S) : Clifford Winings
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:
COL. 15, line 61 [claim 2] after "respectively on" delete "the"; after "second sides" insertthereof; before second occurrence of "first" delete "the" and substitute thereforand
COL. 15, line 62, delete "have a " and substitute thereforhaving; delete "slot" and substitute thereforslots
COL. 15, line 63, after "therein, and" insertwherein
COL. 17, line 45 [claim 23], delete "housing of the receptacle" and substitute thereformounting tab
COL. 18, line 48 [claim 24], delete "comprising;" and substitute thereforecomprising: [delete semi-colon and substitute colon therefor]
COL. 18, line 39, [claim 27], after "between" and before "plug" insertthe
COL. 19, line 10, [claim 30], after "contact" and before "opposing" insert a secondcontact so that lines 9-10 read "the contact portion and the ground contact contact opposing sides"

MAILING ADDRESS OF SENDER (Please do not use customer number below):

WOODCOCK WASHBURN LLP Cira Centre, 12th Floor, 2929 Arch Street Philadelphia, PA 19104

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.